

NATIONAL MINE SAFETY WEEK PROGRAM - BIGE OPERATIONS

Theme: Managing The Critical Controls of Mobile Equipment Risks Date: 28th April – 03rd May

Sunday 28-Apr	Monday 29 - April	Tuesday 30 - April	Wednesday 01-May	Thursday 02-May	Friday 03-May
Day 1	Day 2	Day 3	Day 4	Day 5	Day 6
	Pre-start Meetings Topic	Pre-start Meetings Topic	Pre-start Meetings Topic	Pre-start Meetings Topic	Pre-start Meetings Topic
	Intro to LV & Mobile Equipment Safety	Supervision of Work & Risk	Driver Fitness (Fatigue, Alcohol & Drugs)	Workshop & Maintenance	Vehicle Conditions & Systems
	*Review ICMM vehicle interaction maturity framework *Group Activity: LV / HE Prestart Check *Identifying key components of LV/HV & Mobile Equipment *Specific TMP	**During Prestart: *Speeding * Incorrect selection of Gear * Driving to conditions * Mobile Phone Policy * Demerit Point System * Overtaking * Correct Parking Locations	* Employee Health & Fitness * Medicals * Permit Checks	* How to change tire (Quality Checks) A session for all the drivers on the activity for the day (LV & Heavy Equipment)	* Proper Way to do a prestart check. Quality Checks for LVs / Mobile Equipment s
HAUS BUNG.	Parallel Day Activities				
Introduction for	ASAB Coaching	ASAB Coaching	ASAB Coaching	ASAB Coaching	ASAB Coaching
National Mining Safety Week CEO's Message Key expectations / Targets & Manager's comments Run down of the	RANDOM LV/ HE CHECKS. Supervisors & TL's to lead	RANDOM LV/ HE CHECKS. Supervisors & TL's to lead	RANDOM LV/ HE CHECKS. Supervisors & TL's to lead	RANDOM LV/ HE CHECKS. Supervisors & TL's to lead	RANDOM LV/ HE CHECKS. Supervisors & TL's to lead
	Using the Observation & Interaction (O&I) tool, to intervene and report an unsafe/ safe behavior	Using the Observation & Interaction (O&I) tool, to intervene and report an unsafe/ safe behavior	Using the Observation & Interaction (O&I) tool, to intervene and report an unsafe/ safe behavior	Using the Observation & Interaction (O&I) tool, to intervene and report an unsafe/ safe behavior	Using the Observation & Interaction (O&I) tool, to intervene and report an unsafe/ safe behavior
National Mining Safety week program	Activity of the Day	Activity of the Day	Activity of the Day	Activity of the Day	Activity of the Day
for Bige	 Inspection using the Major Hazard & Key Control Checklists provided on LV Interaction and Use of Highway – drive LMS Awareness Session for Supervisors 	 Review driver's Permits and Licenses LMS Awareness Session for Supervisors 	 Fatigue Points Mental Health Awareness with Sr. Fiona Tuharus 	 Workshop Audit. OTML / Dredeco / LBL EastBank & WestBank 	 Awareness session on prestart checks & changing tiers. Quality Checks for LVs / Mobile Equipment.
	Evening Activity at Kepan Rechall				
	Live Safety Skit	NO session	Mental Health Awareness	No Session	Trivia Night
	Report into INX InControl and share lessons learnt at next prestart meeting.	Report into INX InControl and share lessons learnt at next prestart meeting.	Report into INX InControl and share lessons learnt at next prestart meeting	Report into INX InControl and share lessons learnt at next prestart meeting.	Report into INX InControl and share lessons learnt at next prestart meeting.